EXCEPTIONS-CONTINUED EXCEPTIONS Title Policy Exceptions - Policy No. 676962 - RF58NO2W125390A RECORD OF SURVEY Title Policy Exceptions - Policy No. 676960 - RP56NO2W | 2525 | A Exception 7 - Instrument Number 116194 - Essement granted to GTE Northwest - the right to place buned cable across the SW144 of Section 12, TSBN, R2W - no width - not specifically described location. Exception 10 – Instrument Number 506513 – describes a 60 foot easement across the North 60 feet of RP56N02W125251A. Boundary Line Adjustment Exception 11 – Instrument Number 506926 – Coverants and deed restrictions. It does not contain a description of the property. The coverants to require a 40 building setback. Exception 9 - Instrument Number 506513 - describes a 60 foot easement across the North 60 feet of RP56NO2W125251A. IN THE Exception 12 – Instrument Number 507965 – provides for a 60 floot casement as referenced in Instrument Number 506613 and a 30 floot easement along the East Inne of RP56NO2W125251A. The 30 floot easement straidfies the East property line – 15 feet on each side of the line. Exception 10 - Instrument Number 506926 - Covenants and deed restrictions. It does not contain a description of the property. The covenants to require a 40° building setback. SW1/4 SECTION 12 Exception I.I. - Instrument Number 507965 – provides for a 60 foot easement as referenced in Instrument Number 506518 and a 30 foot easement as not the East large of RFSMOV2W1825114. The 30 foot easement straidles the East property Inc. – 15 feet on each side of the limit. TOWNSHIP 58 NORTH, RANGE 2 WEST, B.M. Except on 13 – Instrument Number 511203 – Warranty Deed describes both RF5ENO2W1252516 and RF5ENO2W125300A. It includes the two essement leated in Instrument Number 507965 (Exception 12) and a 25°C seasement from the South 1/4 content to the South line of RF5ENO2W125390A. BONNER COUNTY, IDAHO Exception 12 Instrument Number 511203 – Warranty Dead describes both RFS6NOZW125261 And RFS6NOZW125390A. It includes the two casements based instrument Marker 507365 (Exception 11) and a 25 casement from the South I/4 corner to the South Ire of RFS6NOZW125300 cont. Thurster 512651 – Record of Survey by PLS 7679 – ublised this survey. FOR Exception 15 - Instrument Number 512851 - Record of Survey by PLS 7879 - whiled this survey. CALDWELL LIVING TRUST 1. 12' 52"E 3 Exception 18 - Instrument Nubmer 664009 - Easement granted to Northern Lights, Inc. across RP58NO2W125251A. No specific location or width. Exception 16 - Instrument Number 831976 - Highway right of way survey by PLS 5087. Utilized this survey. Exception 19 – Instrument Number 831976 – Highway right of way survey by FLS 5087, Utilized this survey. Exception 17 - Instrument Number 935494 – Easement granted to Northern Lights, Inc. generally across Section 12, T58N, R2W – signed in 1952 – recorded in 2009. Exception 20 – Instrument Number 935494 – Easement granted to North-Lights, Inc. generally across Section 12, TS6N, R2W – signed in 1952 – recorded in 2009. 564.95 60' Easement per Instrument No.s 506513, 507965 \$ 511203 (R) N87° 51' 06"W N87° 15' 09"W 18 N82' 29' 12"E Hidden Meadow Lane Sign -Existing 30' Easement 507965 -15' BASIS OF BEARINGS Research are based on Idaho State Plane West Zone (i 103), Bearings are based on Idaho State Plane Wes NAD83 Scale Factor: 0.9998715 All distances shown are converted to ground. 3.77 Acres SURVEYS OF RECORD SURVEYOR FLS NUMBER HICHWAY NO. 95 04.2 N22.28. 8.0 (R) S89" 50" 49"E 664.87 S89" 15" 16"E 664.89 PURPOSE OF SURVEY The purpose of the survey was to adjust the boundary line between RFS0NOWI 25251 and RFS0NOWI 25390A. A survey by PLS 7879 recorded as Instrument Number 51 2851 depicted the boundars of the two proporties lated above. The monuments set by PLS 7879 and PLS 6107 (prevouely set prior to RDS 51 2851) were tied as part of PLS 6107 (prevouely set prior to RDS 51 2851) were tied as part of the sourcy. All moniments from the tied with the recorded survey and the deads of record. A sourcy by PLS 5007 for the Idaho Department of Transportation noted the right of way monuments that were found and ted this survey. Tiesy all its within tolerance. All tied moniments were accepted for the survey. 7115 Old Boundary 9: 12.38 Acres 22 569.09 569.07 3 (R) N20. 20' 27'E N20: 57' 33'E SURVEYOR'S CERTIFICATION S. I. James R. Stayfes, P. I.5 3626, State of Idaho, do hereby certify that the Plat two prepared by me or under my direction and is blast do may prepared by me or under my direction and is blast do may leated in Section 10, I Township 57 Nortin, Ringe i West, of the displant of the Bose Mendain, Bonner Courty, Islaho; that the distances of the Sobern Correctly Herein and that the moments have been placed and all Lot corrects me property set and that the survey is in an all Lot corrects me property set and that the survey is in the placed size of the survey in the surve 330.46 8 03"W 12 ż N89" 14' 18"W (R) N89" 50' 49"W $\begin{array}{cccc} \textbf{COUNTY} & \textbf{RECORDER} \\ \text{This Record of Survey was filed for record in the office of the Recorder of} \end{array}$ 395.59 395.59 This Record of Survey was filed for record in the office of the Reco Bonner County, Idaho, at the request of J.R.S. Surveying, Inc. this LEGEND 8 FOUND CORNER EVIDENCE AS NOTED __day of _______, 2025, at _______m, and duly recorded 03 E 46 E as Instrument No. 395.60 ● FOUND 5/8* REBAR AND CAP PLS 7879 36, A FOUND 5/8" REBAR AND CAP PLS 6 LO7 9 5 ☑ FOUND RIGHT-OF-WAY MONUMENT County Recorder Deputy Recorder 8 SET 5/8" X 30" REBAR AND PLASTIC CAP - PLS 3G28 (R) RECORD BEARING/DISTANCE PER ROS INST. #512851 J.R.S. SURVEYING, INC. PO BOX 3099-6476 MAIN BONNERS FERRY, ID. 83805 (208) 267-7555 RECORD OF SURVEY FOR CALDWELL LIVING TRUST DWN BY: JRS/KLK REVISION NO. 1 DATE: 12/31/2024 S12, TSBN, R2V, B.M.